

Table I-13
Monitoring Site Description

Site	Site 2 - Tipperary Trail	Site 4 - Center Park Road
Land Use	Urban Residential	Industrial
Drainage area, acres	130	95
Sampling Site	60" RCP	42" RCP ¹
Slope (ft/ft)	0.015	0.013
Receiving Stream	Beal Slough	Beal Slough
Rain Gage	Fire Station #8, 2760 S. 17th St.	Fire Station #8, 2760 S. 17th St.

¹ Drainage at the sampling site is through twin 42" RCPs. Sample collected from the west 42" RCP